To: Deyoe, Jeremy[deyoe.jeremy@epa.gov]

From: Riley, Ellen

Sent: Wed 4/30/2014 4:10:42 PM

Subject: FW: EPA Site Visit of BP Whiting Refinery on April 15 - Follow Up Item - Testing Protocol

Valve Testing - letter to EPA - 042914 .pdf

From: Wilson, Linda J (Whiting) [mailto:linda.wilson2@bp.com]

Sent: Tuesday, April 29, 2014 3:51 PM

To: Brown, Jaime; Riley, Ellen; Tzallas, Alexander; Atkociunas, Paul

Cc: Wallace, Jim L; Blanco, Gloria A

Subject: RE: EPA Site Visit of BP Whiting Refinery on April 15 - Follow Up Item - Testing Protocol

As we discussed during your inspection on April 15th, we believe that the backflow protection on a temporary connection between the cooling water system and the brine system failed on March 24th allowing oil into the cooling water system. Attached you will find a testing protocol for the check valves that were supposed to prevent backflow.

<< Valve Testing - letter to EPA - 042914 .pdf>>

Linda Wilson

Environmental Manager

Whiting Business Unit

Office: 219-473-3287

Cell: Ex. 6 - Personal Privacy

This e-mail may contain confidential or proprietary information belonging to the BP group and is intended only for the use of the recipients named above. If you are not the intended recipient, please immediately notify the sender and either delete this email or return to the sender immediately. You may not review, copy or distribute this email. Within the bounds of law, this part of BP retains all emails and IMs and may monitor them to ensure compliance with BP's internal policies and for other legitimate business purposes.

From: Wallace, Jim L [mailto:Jim.Wallace@bp.com]

Sent: Wednesday, April 16, 2014 4:20 PM

To: Brown, Jaime; riley.ellen@epa.gov; tzallas.alexander@epa.gov; atkociunas.paul@epa.gov

Cc: Allendorfer, Robert K.; Wilson, Linda J (Whiting)

Subject: EPA Site Visit of BP Whiting Refinery on April 15 - Follow Up Items

Dear Jaime Brown, Paul Atkociunas, Alex Tzallas, and Ellen Riley

To follow up on your site visit of the BP Whiting Refinery on April 15th, here is a list of follow up items that were discussed in our wrap up session.

- 1) BP to provide a copy of the photos taken on the tour. (Complete Thumb drive with photos provided on April 15.)
- 2) BP to provide a copy of the slides presented on April 15. (Complete Attached to this email.)
- 3) BP to provide the date of when the hose and check valve assembly was installed on 12 Pipestill.
- 4) BP to provide a copy of the incident investigation report. This report should be available in about 60 days from the date of the incident.
- 5) BP to provide a copy of the SPCC Plan.
- 6) BP to provide a letter regarding the status of the Facility Response Plan update.
- 7) BP to submit an updated Facility Response Plan within 60 days of completion date of Whiting WRMP. The WRMP is expected to be completed mid-May 2014.
- 8) BP to complete the post incident response debrief with EPA and USCG.

Please let me know if there are any questions.

I will continue to be the liaison for future information requests.

Jim Wallace

630-536-3431 office



<< File: 2014-04-15 Agenda (BP and EPA).pdf >> << File: CBI - 6SEP Overview - Agency Visit 041514.pdf >> << File: PC - 12PS Overview - Agency Visit 041514.pdf >>